

AL-2 AUTO LOGIC CONTROLLER – SINGLE PHASE

To connect to TEMAC – Ovitor Motor M7162

Wiring Diagram: 1069R4

Connections:

Controller	Motor
Z2	U2
U2	W2
U1	V1
CA	U1
earth	Green/yellow

Connect THERMAL STRIP (N/C O/L) to 38 &39

To reverse rotation, interchange Z2 and CA at the controller

Auxiliary winding: U1 & V2

Run Winding: W2 & V1